What firmware changes have taken place on the Maretron ALM100 Alarm Module?

404 Ron De Pastino April 26, 2022 ALM100, ALM100 0 5.80K

What firmware changes have taken place on the Maretron ALM100 Alarm Module?

Update your device using the N2KAnalyzer software tool paired with a Maretron gateway.

ALM100 Firmware Versions

1.0.6 (2010-08-13)

- Updated supported NMEA 2000 database version to 1.300

1.0.5 (2009-05-20)

- Corrects a stability issue that could arise when multiple alerts are active simultaneously

1.0.4 (2009-02-23)

- Improved support for labeling of the device and its channels to store more pertinent information

1.0.3 (2008-11-26)

- TX 130824 periodically every 10s all the time (if it is not disabled)

1.0.2 (2008-11-05)

- Corrected the reported LEN (Load Equivalent Number) to 2 (100mA maximum)

1.0.1 (2008-10-21)

- Initial public release

Online URL: https://maretron.com/wp-content/phpkbv96/article.php?id=404